Update to Aircraft Inspection, Repair & Alterations

October 2015

AC 43.13-1B and AC 43.13-2B

ASA-AC43.13-1B2B

The FAA originally released AC 43.13-2B in March 2008. In October 2008 an updated version was released resulting in a change to the formula on page 24.

Page Number	Change Explanation
24	AC 43.13-2B, text in the formula was changed in two places from "f.p.s." to "mph":
	V is the V_{NE} of the aircraft in mph. Example: Antenna manufacturer specification frontal area = 0.135 sq. ft. and V_{NE} of aircraft is 250 mph.